


There will not be a lot of stability in the transverse direction. If that is a concern you could make a larger cross beam and/or add some diagonal bracing.

Extend to other side, cantilever will deflect.



I assume this is the heat source. If so it looks pretty far from the structure so I would not expect a lot of problems. However I would try to extend the support and not have a cantilever.