




- Notes:
- 1) Weld in 3/4" PLs first
  - 2) Cut W33 (2'-0" LG Cuts)
  - 3) Weld in 2'-0" LG section of WT

29"

3"

