FF240-IP / Mitel 3300 Interop Testing April 18, 2012


Items tested:


- FF240-IP
 - o Vs. 1.1.15
- Mitel 3300 vs. 5.0 Service Pack 1
 - T.38 license required
 - DSP II card must be installed
 - T.38 fax not supported/recommended in Mitel vs. 4.0 or lower.


Test Results:


• Successfully sent and received single page and three page faxes using T.38 protocol.


Mitel Setup:

















FF240-IP Setup:

• In SIP/T.38 Configuration, configure SIP Proxy/Gateway field with the IP address of the Mitel SIP server. Use default settings in other fields.