




	Motor Current amps	Pressure gauge P1 (bar)	P2 (bar)	P3 (bar)	P4 (bar)
i) Pump-1 in service	70.1	7.76	7.4	4.0	4.3
ii) Pump-2 in service	66.1	8.6	7.9	4.3	4.2
iii) Pump-2 in service Pump-1 MOV passing	83.4	6.5	6.0	2.5	