



$U_Z=0$   
 $U_X = \text{Coupled}$   
 $U_R \text{ all nodes} = 0$

$U_X=U_Z=0$   
 $U_Y = \text{Coupled}$   
 $U_R \text{ all nodes} = 0$

$U_X=U_Y=U_Z= 0$   
 $U_R \text{ all nodes} = 0$



$U_Z=0$   
 $U_X = \text{Coupled}$   
 $U_R \text{ all nodes} = 0$

