



Roof Deformation and an inclined leg support





Clearance between the leg support and its bottom pad



Strange stains inside one of the roof compartments