



$$\uparrow \Sigma F_y = -F_3 \sin \theta - F_{42} \sin \theta + F_1 + F_2 = 0 \quad \dots$$

