



EQUAL TO
FULL FILLET

THREE-PLATE LAP DETAIL

JOINT MUST BE
WELDED UNDER
THE LAP