



ON WHICH CIRCULAR SURFACE SHOULD I LEAVE DATUM TARGET FOR TERTIARY DATUM?



IF MACHINING DATUM REFERENCE FRAME IS A PRIMARY, B OR C SECONDARY, D-M-E TERTIARY, WHAT WOULD BE DATUM FEATURES I PUT DATUM TARGETS ON FOR CASTING?

UNLESS OTHERWISE SPECIFIED
PARAMETRIC MODEL IS CONSIDERED BASIC

ALL CAST SURFACES A AA|AB|AC



DATUM TARGET FEATURES
MOVE TOGETHER
WITH AB2
AND AC2
TO CENTER
AND SET
ROTATION