


Normal Operation

Can't take a wider picture. Basically, the right side of the picture is identical to the left. All nozzles on the right function properly



Pipes with orifice does not show any injection compared to those which doesn't. But there is sound of flow in the pipe when you put your ear on it.

Below of a picture showing a pipe injecting the chemical



Initial thought might be the pipes were choked.

Troubleshooting

Closed the valve on the right side.

Immediately all the injecting pipes on the left shows injection.