


2 FLUTED
SPACERS

new
cement
over top

OLD SLAB



French drain

Seal

VAPOR
BARRIER

2x4
and
Fiber-
glass
insulation
in
between

Cinder
Block

Foundation