

1 Annunciation

1.1 Spontaneous Annunciation - 23.12.2015 16:38:58.584

Spontaneous Annunciation - 23.12.2015 16:38:58.584

Number	Indication	Value	Date and time	Cause
	Selec Swt HSBT Local Pos. Initiate Trans	ON	23.12.2015 16:38:56.359	Spontaneous Com.Issued=AutoLocal
30407	>NORMAL Open CB2	ON	23.12.2015 16:38:56.626	Spontaneous Com.Issued=AutoLocal
17644	NORMAL Start	ON	23.12.2015 16:38:56.629	Spontaneous Com.Issued=AutoLocal
17656	PARALLEL Sequence Close Standby Source	ON	23.12.2015 16:38:56.629	Spontaneous Com.Issued=AutoLocal
17670	Busbar1 -> Line1 is Ready	OFF	23.12.2015 16:38:56.629	Spontaneous Com.Issued=AutoLocal
	Reset LED	OFF	23.12.2015 16:38:56.630	Spontaneous Com.Issued=AutoLocal
00301	Power System fault	23 - ON	23.12.2015 16:38:56.630	Spontaneous Com.Issued=AutoLocal
00302	Fault Event	23 - ON	23.12.2015 16:38:56.630	Spontaneous Com.Issued=AutoLocal
00501	Relay PICKUP	ON	0 ms	Spontaneous Com.Issued=AutoLocal
17767	Command: Close CB1	ON	0 ms	Spontaneous Com.Issued=AutoLocal
30053	Fault recording is running	ON	4 ms	Spontaneous Com.Issued=AutoLocal
	Selec Swt HSBT Local Pos. Initiate Trans	OFF	45 ms	Spontaneous Com.Issued=AutoLocal
17767	Command: Close CB1	OFF	148 ms	Spontaneous Com.Issued=AutoLocal
30407	>NORMAL Open CB2	OFF	653 ms	Spontaneous Com.Issued=AutoLocal
	Selec Swt HSBT Local Pos. Initiate Trans	ON	909 ms	Spontaneous Com.Issued=AutoLocal
17781	Fail: Close CB1	ON	1003 ms	Spontaneous Com.Issued=AutoLocal
17917	Line2 -> Line1 Failed	ON	1003 ms	Spontaneous Com.Issued=AutoLocal
17949	HSBT Failed	ON	1003 ms	Spontaneous Com.Issued=AutoLocal
30456	df at CB closing command triggered	0,02 Hz	0 ms	Spontaneous Com.Issued=AutoLocal
30457	dU at CB closing command triggered	0,2 V	0 ms	Spontaneous Com.Issued=AutoLocal
00501	Relay PICKUP	OFF	1004 ms	Spontaneous Com.Issued=AutoLocal
	Reset LED	OFF	1004 ms	Spontaneous Com.Issued=AutoLocal
00302	Fault Event	23 - OFF	23.12.2015 16:38:57.634	Spontaneous Com.Issued=AutoLocal

Spontaneous Annunciation - 23.12.2015 16:38:58.584(3)

Number	Indication	Value	Date and time	Cause
00301	Power System fault	23 - OFF	23.12.2015 16:38:57.634	Spontaneous Com.Issued=AutoLocal
30053	Fault recording is running	OFF	23.12.2015 16:38:57.744	Spontaneous Com.Issued=AutoLocal
	Selec Swt HSBT Local Pos. Initiate Trans	OFF	23.12.2015 16:38:57.854	Spontaneous Com.Issued=AutoLocal