


c Schematics – 10/12 Pole Self-Excited Generators

VR3 - Current Two Fuse Version

C37582P1



SR-4 GENERATOR SCHEMATIC (10/12 LEAD, SELF-EXCITED & 2 FUSE TYPE)

NOTE : GENERATOR STATOR LEADS TERMINALS T10, T11 AND T12 TO BE CONNECTED TO FORM THE NEUTRAL LEAD (TO) ON 12 LEAD WYE CONNECTED GENERATORS. DELTA CONNECTIONS ONLY AVAILABLE WITH 12 LEAD GENERATORS.