

TEMP REPAIR OF A BROKEN RAIL

SIDE VIEW


HEAD

WEB

FOOT

RAIL

CROSS SECTION:



SUGGESTED
TEMP. SOLUTION