

Figure 6.10 Reduction in Axial Capacity of CHS (Grade 250) Tubular Struts Due to Self Weight




Figure 6.11 Reduction in Axial Capacity of SHS (Grade 350) Tubular Struts Due to Self Weight