



The linkage will be acting about the pin B as indicated, to turn the table which rotates about the same axis. The conveyor is then attached to this turn table. Lets take for now that the 4000kg mass acts through the centre of gravity CG at 3.65m from the axis of rotation. (just assume mass of turntable is negligible for now)