


LAG BOLT EXTENDS PAST
NEUTRAL AXIS



11" MINIMUM

$\frac{1}{2}$ " DIA HOLE @ INSIDE
CORNER OF NOTCH PRIOR TO
CUTTING TO AVOID OVER
NOTCHING BEAM

CONTRACTOR SHALL SEAL
EXPOSED END OF NOTCHED
BEAM WITH WATER REPELLENT
SEALER