

Internal note:  
 Pressure equalising line should be led  
 to the tank bottom for better handling  
 and maintenance of adsorber,  
 pressure equalising valve and drain valve

30UGX03

2 BR010



30LDL01
BR501   d

30LDL01
AT001

30LDL01
BR403   d

30LDL01
BR405   d

30LDL01
AA403
30LDL01
AA404

Internal Note:  
 Condensate drain  
 has to prevent air  
 ingress down  
 to vacuum  
 of -20 mbarg

All tank  
 equipment with  
 Indication "E" =  
 Supply scope of

Condensate  
 storage tank

Internal note:  
 Nozzles N01, N02, N03, N04, N05  
 shall be located in the lower part  
 of the vessel to prevent  
 any supports for handling  
 the valves

Internal note:  
 Syphon is only necessary  
 if CO<sub>2</sub> adsorber is appli-  
 cable;  
 Sophon has to be located  
 inside the vessel to avoid  
 drying out

