

Server:	/sysro/tftp				
	?	ESM_BrowseDlg_Applet			
	?	ESM_FTP_Applet			
	?	ESM_FTP_Client			
	?	ESM_FTP_Display			
	?	globalization			
	?	install			
	?	LMTTestSignals			
	?	script			
	?	symbol			
	+	tftp			
	?	webs			

Dateiname	Dateigröße	Dateityp	Zuletzt geändert	Berechtigu...	Besitzer/Gru...
MINET_6920-enc.st	32.375.787	ST-Datei	19.06.2018	-rwxrwxrwx	system group
MINET_6920.st	31.487.071	ST-Datei	19.09.2017	-rwxrwxrwx	system group
MINET_6930-enc.st	32.684.827	ST-Datei	19.06.2018	-rwxrwxrwx	system group
MINET_6930.st	32.143.931	ST-Datei	19.09.2017	-rwxrwxrwx	system group
MINET_6940-enc.st	34.326.267	ST-Datei	19.06.2018	-rwxrwxrwx	system group
MINET_6940.st	33.656.743	ST-Datei	19.09.2017	-rwxrwxrwx	system group

1 Folder MiVoice Business

6940
Log Out

Status
System Information
License Status
Operation
User Password
Phone Lock
Softkeys and XML
Keypad Speed Dial
Directory
Reset
Basic Settings
Preferences
Account Configuration
Custom Ringlines
Advanced Settings
Network
Cloud Service
Global SIP
Line 1
Line 2
Line 3
Line 4
Line 5
Line 6
Line 7
Line 8
Line 9
Line 10
Line 11
Line 12
Line 13
Line 14
Line 15
Line 16
Line 17
Line 18
Line 19
Line 20
Line 21
Line 22
Line 23
Line 24
Action URI
Configuration Server
Firmware Update
TLS Support
802.1x Support
Troubleshooting
Capture
Parameter Filter
Diagnostics
Screenshot

Manual Firmware Update
Enter the server's IP address and the name of the firmware below to initiate a firmware update.
File Name:
Download Protocol:
Server:
Path:
Port:
Username:
Password:

2 Website 6940

MiVoice Business > Firmware > 69xx FW 1.5.3.23 For MiVB 9.1 SP1			Filter
	69xx (rpm) Firmware for MiVB 9.1 SP1 or MBG	mitel-phoneloads-69xx-1.5.3.23-1.noarch.rpm	Software
	69xx (tar) for MiVB 8.0	mitel-phoneloads-69xx.tar	Software
	69xx FW update tool for MiVB 8.0 SP1-8.0SP3 PRx	MiVB8.0FWUpdateTool.zip	Software

3 Example Firmware Download MiAccess