


Current Condition



Potential Option for steel lintel

