



CHAMPLAIN TOWERS SOUTH 40-YEAR BUILDING

REPAIR & RESTORATION

PHASE I: OVERALL BUILDING

PHASE II: OVERSIGHT BUILDING

REPAIR AND RESTORATION

SEAL

License: 89069-EE: 89035
Expires: 02/28/98

(1)

This item has been digitally signed and sealed by Autodesk, Inc. The seal is a digital signature that is unique to each copy of the software. It is not considered signed and sealed if the seal is damaged or altered in any way.

B-1

momorabito

Structural Engineers & Architects Consulting Consultants
1000 Via Conza Drive, Suite 200, San Ramon, CA 94583-1701
Tel: 925-391-1116 Fax: 925-391-1117
www.momorabito.com
Copyright © 2000 Momorabito Consulting Consultants, Inc.

No.	Date	Revised

DESIGNED DRAWN
HR/JB/RM/RM/RJ/BW/RM/RM

CHECKED RM APPR VER FPM FPM

Project No. 178217

Date: 2/26/01

Scale: 3/32" = 1'-0"

Sheet Title:
BASE LEVEL / DEMO PLAN

Sheet No.:
A20C51.0