



- The three shapes are orthogonal views of a part.
- One internal line is missing from one of the views.
- Draw the missing line and the isometric view of the part.

