


QSA Camera Evaluation picture update



Camera 7551 showing wear in the S-Tube



Camera 7551 showing wear in the S-Tube




Camera 7551 showing wear in the S-Tube




Camera 7551 showing wear in the S-Tube






Picture showing what appears to be wear into the DU on camera 7551



Picture showing what appears to be wear into the DU on camera 7551



Transverse picture showing depth of wear DU on camera 7551



Camera C1137-D09 showing cracks in the S-Tube




Camera C1137-D09 showing cracks and interior wall defects in the S-Tube





Camera C1137-D09 showing cracks and interior wall defects in the S-Tube



Higher magnification of Camera C1137-D09 showing cracks and interior wall defects in the S-Tube



Higher magnification of Camera C1137-D09 showing cracks and interior wall defects in the S-Tube



Micrograph of Camera C1137-D09 showing cracks on the interior wall of the S-Tube