


ANCHOR #2



* WE HAVE TRIED TO GROUT THIS AREA 6 TIMES. IT STILL COLLAPSES ON US WHEN RE-HAMMERING. ANY SUGGESTIONS,

WE CAN'T TURN CASING ANYMORE, AFTER OUR 1ST GROUT ATTEMPT WE GROUTED IT IN.